

**Doraig Cottage  
Onich  
Fort William  
PH33 6SD**



Inspected on: 31<sup>st</sup> March 2025

**Prepared by:**  
Samuel & Partners  
First Surveyors Scotland  
First Floor  
20 High Street  
FORT WILLIAM  
PH33 6AT

# Home Report Index

1. Property Questionnaire
2. Single Survey
3. Mortgage Valuation
4. Energy Report

# Property Questionnaire

PROPERTY ADDRESS:	<b>Doraig Cottage &amp; adjoining plot Onich Fort William PH33 6SD</b>
SELLER(S):	<b>Andrew Richard Taylor Linda Susan Taylor</b>
COMPLETION DATE OF PROPERTY QUESTIONNAIRE:	<b>21.03.25</b>

# PROPERTY QUESTIONNAIRE

Information to be given to prospective buyer(s)

1.	Length of ownership	
	How long have you owned the property? <b>20 years</b>	
2.	Council Tax	
	Which Council Tax band is your property in? A B C <b><u>D</u></b> E F G H	
3.	Parking	
	<p>What are the arrangements for parking at your property? (Please indicate all that apply)</p> <ul style="list-style-type: none"> <li>• <b>Garage</b>✓</li> <li>• Allocated parking space</li> <li>• <b>Driveway</b>✓</li> <li>• Shared parking</li> <li>• On street</li> <li>• Resident permit</li> <li>• Metered parking</li> <li>• Other (please specify):</li> </ul>	
4.	Conservation Area	
	Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)?	<b>Don't know</b>
5.	Listed Buildings	
	Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)?	<b>No</b>
6.	Alterations / additions / extensions	
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	<b>Yes</b>
	<b>If you have answered yes</b> , please describe the changes which you have made: <b>Put bathroom in upstairs and made downstairs open plan</b>	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	<b>Yes</b>

	<p><b><u>If you have answered yes</u></b>, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.</p> <p><b>With our solicitors</b></p> <p>If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent can arrange to obtain them.</p>	
b.	<p>Have you had replacement windows, doors, patio doors or double glazing installed in your property?</p> <p><b><u>If you have answered yes</u></b>, please answer the three questions below:</p>	<b>No</b>
	(i) Were the replacements the same shape and type as the ones you replaced?	
	(ii) Did this work involve any changes to the window or door openings?	
	<p>(iii) Please describe the changes made to the windows, doors, or patio doors (with approximate dates when the work was completed):</p> <p>Please give any guarantees which you received for this work to your solicitor or estate agent.</p>	
<b>7.</b>	<b>Central heating</b>	
a.	<p>Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom).</p> <p><b><u>If you have answered yes/partial</u></b> – what kind of central heating is there? <b>Electric storage heating</b> (Examples: gas-fired, solid fuel, electric storage heating, gas warm air.)</p>	<b>Partial</b>
	<b><u>If you have answered yes, please answer the 3 questions below:</u></b>	
b.	When was your central heating system or partial central heating system installed? <b>1990</b>	
c.	<p>Do you have a maintenance contract for the central heating system?</p> <p><b><u>If you have answered yes</u></b>, please give details of the company with which you have a maintenance agreement:</p>	<b>No</b>
d.	When was your maintenance agreement last renewed? (Please provide the month and year).	
<b>8.</b>	<b>Energy Performance Certificate</b>	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	<b>No</b>
<b>9.</b>	<b>Issues that may have affected your property</b>	
a.	<p>Has there been any storm, flood, fire or other structural damage to your property while you have owned it?</p> <p><b><u>If you have answered yes</u></b>, is the damage the subject of any outstanding insurance claim?</p>	<b>No</b>

b.	Are you aware of the existence of asbestos in your property? <u>If you have answered yes</u> , please give details:	No																								
<b>10. Services</b>																										
a.	Please tick which services are connected to your property and give details of the supplier:																									
	<table border="1"> <thead> <tr> <th>Services</th> <th>Connected</th> <th>Supplier</th> </tr> </thead> <tbody> <tr> <td>Gas / liquid petroleum gas</td> <td></td> <td></td> </tr> <tr> <td>Water mains / private water supply</td> <td>✓</td> <td></td> </tr> <tr> <td>Electricity</td> <td>✓</td> <td>OVO</td> </tr> <tr> <td>Mains drainage</td> <td></td> <td></td> </tr> <tr> <td>Telephone</td> <td>✓</td> <td></td> </tr> <tr> <td>Cable TV / satellite</td> <td></td> <td></td> </tr> <tr> <td>Broadband</td> <td>✓</td> <td>Vodafone</td> </tr> </tbody> </table>	Services	Connected	Supplier	Gas / liquid petroleum gas			Water mains / private water supply	✓		Electricity	✓	OVO	Mains drainage			Telephone	✓		Cable TV / satellite			Broadband	✓	Vodafone	
Services	Connected	Supplier																								
Gas / liquid petroleum gas																										
Water mains / private water supply	✓																									
Electricity	✓	OVO																								
Mains drainage																										
Telephone	✓																									
Cable TV / satellite																										
Broadband	✓	Vodafone																								
b.	Is there a septic tank system at your property? <u>If you have answered yes</u> , please answer the two questions below:	Yes																								
c.	Do you have appropriate consents for the discharge from your septic tank?	Yes																								
d.	Do you have a maintenance contract for your septic tank? <u>If you have answered yes</u> , please give details of the company with which you have a maintenance contract:	No																								
<b>11. Responsibilities for Shared or Common Areas</b>																										
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? <u>If you have answered yes</u> , please give details:	No																								
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? <u>If you have answered yes</u> , please give details:	N/A																								
c.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	No																								

d.	Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?  <u>If you have answered yes</u> , please give details:	No
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?  <u>If you have answered yes</u> , please give details:	No
f.	As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.)  <u>If you have answered yes</u> , please give details:	No
<b>12. Charges associated with your property</b>		
a.	Is there a factor or property manager for your property?  <u>If you have answered yes</u> , please provide the name and address and give details of any deposit held and approximate charges:	No
b.	Is there a common buildings insurance policy?  <u>If you have answered yes</u> , is the cost of the insurance included in your monthly/annual factor's charges?	No
c.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, e.g. to a Residents' Association, or maintenance or stair fund.	None
<b>13. Specialist Works</b>		
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?  <u>If you have answered yes</u> , please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property	No
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?  <u>If you have answered yes</u> , please give details	No

c.	<p>If you have answered <u>yes</u> to 13(a) or (b), do you have any guarantees relating to this work?</p> <p>If you have answered <u>yes</u>, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write below who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.</p> <p>Guarantees are held by:</p>						N/A
<b>14. Guarantees</b>							
a.	Are there any guarantees or warranties for any of the following:						
(i)	Electrical work	No	Yes	Don't Know	With title deeds	Lost	
(ii)	Roofing	No	Yes	Don't Know	With title deeds	Lost	
(iii)	Central heating	No	Yes	Don't know	With title deeds	Lost	
(iv)	NHBC	No	Yes	Don't know	With title deeds	Lost	
(v)	Damp course	No	Yes	Don't know	With title deeds	Lost	
(vi)	Any other work or installations? (e.g: cavity wall insulation, underpinning, indemnity policy)	No	Yes	Don't know	With title deeds	Lost	
b.	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):						
c.	<p>Are there any outstanding claims under any of the guarantees listed above?</p> <p>If you have answered <u>yes</u>, please give details:</p>						No
<b>15. Boundaries</b>							
<p>So far as you are aware, has any boundary of your property been moved in the last 10 years?</p> <p>If you have answered <u>yes</u>, please give details:</p>						No	
<b>16. Notices that affect your property</b>							
In the past 3 years have you ever received a notice:							
a.	advising that the owner of a neighbouring property has made a planning application?						
b.	that affects your property in some other way?						
c.	that requires you to do any maintenance, repairs or improvements to your property?						

<b>If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.</b>	
---	--

**Declaration by the seller(s)/or other authorised body or person(s):**

**I / We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.**

**Signature(s) :**

.....**L Taylor**.....

.....**A Taylor**.....

**Date:** .....**21.03.25**.....

# single survey

## survey report on:

<b>Property address</b>	Doraig Cottage Onich Fort William PH33 6SD
-------------------------	---

<b>Customer</b>	Linda & Andrew Taylor
-----------------	-----------------------

<b>Customer address</b>	18 Galloway Crescent Broxburn West Lothian EH52 6XN
-------------------------	--

<b>Prepared by</b>	John Strachan MRICS Samuel & Partners - FS Scotland
--------------------	---

<b>Date of Inspection</b>	31 <sup>st</sup> March 2025
---------------------------	-----------------------------

## 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without the need to move any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right are taken facing the front of the property.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc were not inspected or reported on.

Description	A detached dwelling house.
Accommodation	<b>Ground floor:</b> entrance hall, open plan living, kitchen and dining, bedroom and a shower room. <b>First floor:</b> landing, 2 bedrooms and a bathroom.
Gross internal floor area (m <sup>2</sup> )	90 sq m.
Neighbourhood and location	The property is set within the village of Onich 10 miles south of the town of Fort William. The village of Onich comprises of similar type privately owned houses and small agricultural holdings. All essential services, amenities and transport links are available within the regional centre town of Fort William.
Age	The property was extensively altered and refurbished in 1993. Some original parts of the property may possibly be around 90 years of age.
Weather	Dry and sunny. The preceding weather was similar.
Chimney stacks	<i>Visually inspected with the aid of binoculars where appropriate</i> None.
Roofing including roof space	<i>Sloping roofs were visually inspected with the aid of binoculars where appropriate</i> <i>Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3 m ladder externally</i> <i>Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3 m ladder within the property</i> <i>If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so</i> The roof is pitched and covered in a concrete tile. The ridge is in a concrete tile. The verges are cloaked in a upvc trim. There are Velux rooflights to the front and rear.  Due to the nature of construction of the first floor attic accommodation remaining roof spaces are limited. We were unable to view the lower roof spaces as the access hatches were locked. We viewed the upper roof space via a ceiling hatch to the left hand bedroom. The roof is of factory timber manufactured roof trusses with a sterling board sarking. There is glass wool insulation between the ceiling joists. The roof space houses the cold water storage tank.
Rainwater fittings	<i>Visually inspected with the aid of binoculars where appropriate</i> Upvc gutters and downpipes. The downpipes discharge to grated gullies.
Main walls	<i>Visually inspected with the aid of binoculars where appropriate</i> <i>Foundations and concealed parts were not exposed or inspected</i> The external walls appear to be in cavity masonry construction. These are finished externally in a wet dash render or smooth render. It would appear that parts of the external walls are in poured insitu concrete construction. See legal matters.  Internal surfaces are lined in plasterboard.


# single survey

Windows, external doors and joinery	<p><i>Internal and external doors were opened and closed where keys were available</i></p> <p><i>Random windows were opened and closed where possible</i></p> <p><i>Doors and windows were not forced open</i></p> <p>Windows are in timber frame and casement with sealed double glazed panels. The front door is in replacement upvc. There is a sliding upvc patio door to the rear.</p> <p>The fascia and barge boards are in timber. The soffit to the overhang to the rear is lined in timber. The rafter feet and outriggers are exposed as a finish.</p>
External decorations	<p><i>Visually inspected</i></p> <p>Windows, fascia, soffit and barge boards are painted. The walls have a masonry paint finish.</p>
Conservatories/porches	<p><i>Visually inspected</i></p> <p>None</p>
Communal areas	<p><i>Circulation areas visually inspected</i></p> <p>None</p>
Garages and permanent outbuildings	<p><i>Visually inspected</i></p> <p>There is an outbuilding to the rear. The walls are mainly in solid masonry construction. There is an area of timber and corrugated iron sheets. The roof is pitched and covered in metal corrugated sheet. There are double timber doors. We did not enter the outbuilding as it was padlocked at the time of inspection.</p>
Outside areas and boundaries	<p><i>Visually inspected</i></p> <p>There are garden grounds mainly to the rear and side. These are flat and covered in grass and bordered in tress and hedging. There are stone retaining walls to the front and rear. There is a stone chipped drive to the side with double galvanised gates.</p> <p>Boundaries are in timber, metal and hedgerow.</p>
Ceilings	<p><i>Visually inspected from floor level</i></p> <p>Plasterboard lined throughout. There is an Artex finish in places.</p>
Internal walls	<p><i>Visually inspected from floor level</i></p> <p><i>Using a moisture meter, walls were randomly tested for dampness where considered appropriate</i></p> <p>Timber frame with plasterboard linings.</p>
Floors including sub floors	<p><i>Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted</i></p> <p><i>Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point</i></p> <p><i>Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1 m between the underside of floor joists and the solum as determined from the access hatch</i></p> <p>The ground floor would appear to be in solid concrete with a floating timber floor. The first floor is in boarded joists. Floors were fully covered and carpeted at the time of inspection. There is no sub floor space.</p>
Internal joinery and kitchen fittings	<p><i>Built in cupboards were looked into but no stored items were moved</i></p> <p><i>Kitchen units were visually inspected excluding appliances</i></p> <p>Facings and skirtings are in timber. Internal doors are in timber six panel. The stair is in timber construction in one straight flight. The stair is carpeted and the underside is lined in plasterboard.</p> <p>Kitchen fittings are modern and comprise of a proprietary range of plastic vinyl faced base and wall units with a proprietary worktop, inset sink and integral hob and oven housing.</p>
Chimney breasts and fireplaces	<p><i>Visually inspected</i></p> <p><i>No testing of the flues or fittings were carried out</i></p> <p>None.</p>
Internal decorations	<p><i>Visually inspected</i></p> <p>Ceilings and walls have an emulsion paint finish. Internal joinery is stained.</p>
Cellars	<p><i>Visually inspected where there was a safe and purpose built access</i></p> <p>None</p>

# single survey

Electricity	<p><i>Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on</i></p> <p>Mains electricity supply. The meter and fuse boards are located within the cupboard to the ground floor bedroom. Electrical fittings are modern.</p>
Gas	<p><i>Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on</i></p> <p>None</p>
Water, plumbing, bathroom fittings	<p><i>Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances</i></p> <p>Mains water supply. We did not locate the incoming rising main. Plumbing supplies where viewed are in copper, wastes are in plastic.</p> <p>The shower room fittings are new and comprise of a ceramic wc, ceramic wash hand basin and a proprietary shower enclosure. Surfaces within the shower are in a wet wall. There is a thermostatic mixer shower.</p> <p>Fittings to the first floor bathroom appear original and comprise of a ceramic wc, ceramic wash hand basin and an acrylic bath. There is a mixer tap and handset to the bath. Surfaces within the bathroom are tiled.</p>
Heating and hot water	<p><i>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances</i></p> <p>There is partial electric central heating via individual panel heaters. A newer style radiator has been fitted to the living room. There is electric underfloor heating to the ground floor shower room.</p> <p>Hot water is heated and stored in a stainless steel cylinder located within the cupboard to the ground floor bedroom.</p>
Drainage	<p><i>Drainage covers etc were not lifted. Neither drains nor drainage systems were tested</i></p> <p>Drainage connects to a masonry septic tank located on ground to the side of the property.</p>
Fire, smoke and burglar alarms	<p><i>Visually inspected. No tests whatsoever were carried out to the system or appliances</i></p> <p>There are no fire or burglar alarms. There are smoke/heat detectors in places.</p> <p>Fire Safety Legislation effective from February 2022 requires a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat detection alarm must be installed in every kitchen area and all smoke and heat alarms must be ceiling mounted and interlinked. Where there is a carbon fuelled appliance e.g. central heating boiler, open fire, wood burning stove, etc, a carbon monoxide detector is also required. The purchaser(s) should appraise themselves of the requirements of this legislation and engage with appropriate accredited contractors to ensure compliance.</p>
Any additional limits to inspection	<p><i>For flats/maisonettes. Only the subject flat and internal communal areas giving access to the flat were inspected</i></p> <p><i>If the roof space or underbuilding/basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation</i></p> <p><i>The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance</i></p> <p><i>We have not carried out an inspection for Japanese Knotweed or other invasive plant species and unless otherwise stated for the purpose of this report we have assumed that there is no Japanese Knotweed or other invasive plant species within the boundaries of the property or in neighbouring properties. the identification of Japanese Knotweed or other invasive plant species should be made by a Specialist Contractor.</i></p> <p>As mentioned above access to the roof space was limited.</p> <p>The floors were fully covered and carpeted at the time of inspection. The property was also furnished at the time of inspection.</p>

## Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

## 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3		Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.		Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.
Structural movement			
Repair category	1		
Notes	No evidence of any significant cracking, current settlement and no conditions present to suggest the foundations are defective or inadequate.		
Dampness, rot and infestation			
Repair category	1		
Notes	No evidence of any significant damp, rot or infestation in any areas inspected.		
Chimney stacks			
Repair category	Not applicable		
Notes			
Roofing including roof space			
Repair category	1		
Notes	No evidence of any significant disrepair. There is moss holding to the roof tiles in places. The roof tiles are around 32 years of age.  The verge trim to the base of the left hand gable has been cut short, presumably to accommodate a former overhead cable.  Insulation within the upper roof space is a little bit untidy in places.		
Rainwater fittings			
Repair category	1		
Notes	No evidence of any significant disrepair.		
Main walls			
Repair category	1		
Notes	No immediate action required. There is some minor fine hairline cracking to the render typically on the rear elevation but this is not significant. It would appear there is some small isolated boss (debonded) areas of render to the right hand gable.		
Windows, external doors and joinery			
Repair category	1		
Notes	Although no obvious repairs are required the windows are more than 30 years of age. Some softening/rot is beginning to start to the ends of the timber threshold to the front door.		
External decorations			
Repair category	2		
Notes	The decorations to the barge board on the exposed left facing gable elevation has weathered.		

# single survey

<b>Conservatories/porches</b>	
Repair category	Not applicable
Notes	
<b>Communal areas</b>	
Repair category	Not applicable
Notes	
<b>Garages and permanent outbuildings</b>	
Repair category	2
Notes	The fabric of the outbuilding is fairly worn. We suspect the corrugated iron roof will require replacing fairly soon. There is rot to some external woodwork.
<b>Outside areas and boundaries</b>	
Repair category	1
Notes	No immediate action required. The ground to the side of the drive is retained with concrete slabs. A number of these are beginning to lean. The Terram to the stone chipped drive is showing in places. It is good practice to check the health of mature trees to the rear garden on a regular basis.  There is wear to the boundary fencing in places.
<b>Ceilings</b>	
Repair category	1
Notes	No evidence of any significant disrepair. There is a small indent to the plasterboard coombe to the first floor right hand bedroom.
<b>Internal walls</b>	
Repair category	1
Notes	No evidence of any significant disrepair. Some screw fixings show to the plasterboard walls in places. These can be made good at the next redecorations.
<b>Floors including sub-floors</b>	
Repair category	1
Notes	No evidence of any significant disrepair having regard to the limits of our inspection.
<b>Internal joinery and kitchen fittings</b>	
Repair category	1
Notes	No evidence of any significant disrepair.
<b>Chimney breasts and fireplaces</b>	
Repair category	Not applicable.
Notes	
<b>Internal decorations</b>	
Repair category	1
Notes	No significant wear. Some Ames taping has split or delaminated to the plasterboard joints in places. The extent of any redecorations will become more apparent once the house is cleared of all household goods, furniture, wall hangings, etc.
<b>Cellars</b>	
Repair category	Not applicable
Notes	

# single survey

Electricity	
Repair category	2
Notes	Although probably in an acceptable condition there is a record on a fuse board confirming that an electrical test was due in 2020.  It is good practice to test electrical installations to domestic properties on a 5 year cycle or upon an exchange of ownership.
Gas	
Repair category	Not applicable
Notes	
Water, plumbing and bathroom fittings	
Repair category	1
Notes	No evidence of any significant disrepair.
Heating and hot water	
Repair category	1
Notes	No immediate action required. The panel heaters are around 30 years of age which is around the life expectancy of this type of heater. The property would benefit from a more modern and comprehensive form of heating.
Drainage	
Repair category	1
Notes	No evidence of any significant disrepair having regard to the limits of our inspection. The concrete haunching around the slab over the opening to the septic tank is defective. It is good practice to service/de-sludge septic tanks on a regular basis.

# single survey

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	N/a
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	2
Conservatories / porches	N/a
Communal areas	N/a
Garages and permanent outbuildings	2
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	N/a
Internal decorations	1
Cellars	N/a
Electricity	2
Gas	N/a
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

## Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

## Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

## Category 1

No immediate action or repair is needed.

### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

## 3. Accessibility information

### Guidance notes on accessibility information

*Three steps or fewer to a main entrance door of the property:* In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

*Unrestricted parking within 25 metres:* For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground floor
2. Are there three steps or fewer to a main entrance door of the property?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
3. Is there a lift to the main entrance door of the property?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
4. Are all door openings greater than 750mm?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
5. Is there a toilet on the same level as the living room and kitchen?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
6. Is there a toilet on the same level as a bedroom?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
7. Are all rooms on the same level with no internal steps or stairs?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

## 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

### Matters for a solicitor or licensed conveyancer

It is assumed that the subjects are held on an absolute ownership basis [formerly feudal]. This should be confirmed by your solicitor.

In addition to the standard searches and enquiries to be carried out by your solicitor we would recommend that the following matters are confirmed:

1. Statutory consent would have been required for the works carried out around 1993. The approved building warrant drawings will confirm the construction of the property. If the walls are in poured concrete construction throughout, then the property might be considered as being of a non traditional form of construction. This could affect future saleability. This should be checked.
2. Has the septic tank been de-sludged recently?

### Estimated reinstatement cost for insurance purposes

It is recommended that the subjects be insured for a sum of not less than £320,000 [three hundred & twenty thousand pounds] (to include the outbuilding).

This figure is the estimate of the cost of rebuilding the property and bears no direct relationship to the current market value.

### Valuation and market comments

**£290,000** [two hundred & ninety thousand pounds]

There is a strong demand for properties of this size and type within the village of Onich.

Report author	John Strachan MRICS
Address	Samuel & Partners FS Scotland, First Floor, 20 High Street, Fort William, Scotland, PH33 6AT
Signed	Electronically prepared by Samuel & Partners
Date of report	02 April 2025

# Terms and Conditions

## PART 1 - GENERAL

### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report is transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

☐

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

---

<sup>1</sup> Which shall be in accordance with the current RIGS Valuation Standards (The Red Book) and RIGS Rules of Conduct.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### **1.4 INTELLECTUAL PROPERTY**

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### **1.5 PAYMENT**

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### **1.6 CANCELLATION**

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

#### **1.7 PRECEDENCE**

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### **1.8 DEFINITIONS**

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;

- a "prospective Purchaser" is anyone considering buying the Property;
  - the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
  - the "Seller" is/are the proprietor(s) of the Property;
  - the "Surveyor" is the author of the Report on the Property; and
  - the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- + the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

## **PART 2 - DESCRIPTION OF THE REPORT**

### **2.1 THE SERVICE**

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company.

### **2.2 THE INSPECTION**

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

### **2.3 THE REPORT**

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

1. Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
3. Category 1: No immediate action or repair is needed.

**WARNING:**

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

## **2.4 SERVICES**

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances

## **2.5 ACCESSIBILITY**

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

## **2.6 ENERGY REPORT**

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

## **2.7 VALUATION AND CONVEYANCER ISSUES**

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- \* There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

# Samuel & Partners

## Generic Valuation

### Mortgage Valuation Report

<b>Property:</b>	Doraig Cottage Onich Fort William PH33 6SD	<b>Customer:</b>	
		<b>Owner:</b>	
		<b>Introducer:</b>	
		<b>Tenure:</b>	Standard Ownership (assumed)
<b>Date of Inspection:</b>	31.03.25	<b>Reference:</b>	

*This Mortgage Valuation Report has been issued as part of The Home Report prepared on the property referred to above. This report and associated Home Report together with the inspection has been carried out in accordance with the RICS Appraisal and Valuation Standards (The Red Book) and the RICS Rules of Conduct. Potential purchasers must not read this report in isolation and your attention is drawn to the additional comments contained in The Single Survey and also the Terms and Conditions of the associated Home Report. This report has been prepared solely for mortgage lenders to consider the property's suitability for mortgage finance. Your attention is also drawn to the fact that neither the whole nor any part of the report or any reference thereto may be included in any document, circular or statement without prior approval in writing as to the form in which it will appear.*

<b>1.0</b>	<b>LOCATION</b>
------------	-----------------

The property is set within the village of Onich 10 miles south of the town of Fort William. All essential services, amenities and transport links are available within the regional centre town of Fort William.

<b>2.0</b>	<b>DESCRIPTION</b>	<b>2.1 Age:</b>	1930	
------------	--------------------	-----------------	------	--

A detached dwelling house. The property was extensively altered, extended and refurbished in 1993.

<b>3.0</b>	<b>CONSTRUCTION</b>
------------	---------------------

Cavity/solid masonry walls; pitched and tiled roof; concrete and timber floors

<b>4.0</b>	<b>ACCOMMODATION</b>
------------	----------------------

**Ground floor:** entrance hall, open plan living, kitchen and dining, bedroom and a shower room.  
**First floor:** landing, 2 bedrooms and a bathroom.

<b>5.0</b>	<b>SERVICES</b> (No tests have been applied to any of the services)						
------------	---	--	--	--	--	--	--

<b>Water:</b>	Mains	<b>Electricity:</b>	Mains	<b>Gas:</b>	None	<b>Drains:</b>	Private
---------------	-------	---------------------	-------	-------------	------	----------------	---------

**Central Heating:** Partial – electric storage and panel heaters.

<b>6.0</b>	<b>OUTBUILDINGS</b>
------------	---------------------

<b>Garage:</b>	None
----------------	------

<b>Others:</b>	Masonry constructed outbuilding.
----------------	----------------------------------

<b>7.0</b>	<b>GENERAL CONDITION</b> - <i>A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.</i>
------------	--

The property is in a good condition for lending purposes.

<b>8.0</b>	<b>ESSENTIAL REPAIR WORK</b> (as a condition of any mortgage or, to preserve the condition of the property)				
None required as a condition of the mortgage					
<b>8.1 Retention recommended:</b>			Reflected in the valuation.		
<b>9.0</b>	<b>ROADS &amp; FOOTPATHS</b>				
Have the roads and footpaths adjacent to the property been adopted and maintained by the Local Authority?			<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<i>If No, comment to be made in Section 11</i>
<b>10.0</b>	<b>BUILDINGS INSURANCE</b>	£320,000	<b>GROSS EXTERNAL FLOOR AREA</b>	96	Sq m
<i>This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.</i>					
<b>11.0</b>	<b>GENERAL REMARKS</b>				
Drainage is to a masonry septic tank.					
<b>12.0</b>	<b>VALUATION</b> <i>On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.</i>				
<b>12.1</b>	<b>Market Value in present condition</b>	<b>£290,000</b>	Two hundred & ninety thousand pounds		
<b>12.2</b>	<b>Market Value on completion of essential works:</b>	<b>£</b>	<i>See remarks in Section 11 of this report.</i>		
<b>12.3</b>	<b>Suitable security for normal mortgage purposes?</b>	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
<b>Signature</b>		Electronically signed = John Strachan			
<b>Surveyor:</b>		John Strachan, MRICS		<b>Date:</b>	2 April 2025
<b>Surveyor Company:</b>		Samuel & Partners, First Surveyors Scotland			
<b>Address:</b>		First Floor, 20 High Street Fort William, PH33 6AT			
<b>Telephone:</b>		01397 702686			
<b>E-mail</b>		info@samuelandpartners.co.uk			

# Energy Performance Certificate (EPC)

# Scotland

Dwellings

**DORAIG COTTAGE, ONICH, FORT WILLIAM, PH33 6SD**

**Dwelling type:** Detached house  
**Date of assessment:** 31 March 2025  
**Date of certificate:** 03 April 2025  
**Total floor area:** 90 m<sup>2</sup>  
**Primary Energy Indicator:** 350 kWh/m<sup>2</sup>/year

**Reference number:** 7497-1022-3207-7165-9204  
**Type of assessment:** RdSAP, existing dwelling  
**Approved Organisation:** Elmhurst  
**Main heating and fuel:** Room heaters, electric

## You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

**Estimated energy costs for your home for 3 years\***

**£6,879**


See your  
recommendations  
report for more  
information

**Over 3 years you could save\***

**£2,946**

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions

Very energy efficient - lower running costs



Current	Potential
53	61

## Energy Efficiency Rating


This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band E (53)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Not energy efficient - higher running costs

Very environmentally friendly - lower CO<sub>2</sub> emissions



Current	Potential
49	59

## Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band E (49)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Not environmentally friendly - higher CO<sub>2</sub> emissions

## Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Floor insulation (solid floor)	£4,000 - £6,000	£507.00
2 High heat retention storage heaters	£1,600 - £2,400	£2160.00
3 Solar water heating	£4,000 - £6,000	£282.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit [greenerscotland.org](http://greenerscotland.org) or contact Home Energy Scotland on 0808 808 2282.

**THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, with internal insulation	★★★★☆	★★★★☆
Roof	Roof room(s), insulated	★★★★☆	★★★★☆
Floor	Solid, limited insulation (assumed)	—	—
Windows	Fully double glazed	★★★☆☆	★★★☆☆
Main heating	Room heaters, electric	★☆☆☆☆	★★☆☆☆
Main heating controls	Programmer and appliance thermostats	★★★★☆	★★★★☆
Secondary heating	Room heaters, electric	—	—
Hot water	Electric immersion, off-peak	★★☆☆☆	★★☆☆☆
Lighting	Low energy lighting in all fixed outlets	★★★★★	★★★★★

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.


## The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 59 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 5.3 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.5 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.









## Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£5,505 over 3 years	£3,078 over 3 years	
Hot water	£1,041 over 3 years	£534 over 3 years	
Lighting	£333 over 3 years	£321 over 3 years	
<b>Totals</b>	<b>£6,879</b>	<b>£3,933</b>	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

## Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures	Indicative cost	Typical saving per year	Rating after improvement	
			Energy	Environment
1 Floor insulation (solid floor)	£4,000 - £6,000	£169		
2 High heat retention storage heaters	£1,600 - £2,400	£720		
3 Solar water heating	£4,000 - £6,000	£94		
4 Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£391		

### Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Biomass boiler (Exempted Appliance if in Smoke Control Area)
- Air or ground source heat pump

## Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to [www.greenerscotland.org](http://www.greenerscotland.org).

## About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

### 1 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including [www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation](http://www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation). Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

### 2 High heat retention storage heaters

Modern storage heaters are less expensive to run than the direct acting, on-peak heating system in the property. A dual-rate electricity supply is required to provide the off-peak electricity that these heaters use; this is easily obtained by contacting the energy supplier. Ask for a quotation for high heat retention with automatic charge and output controls. Installations should be in accordance with the national wiring standards. Building regulations generally apply to this work and a building warrant may be required, so it is best to obtain advice from your local authority building standards department and from a qualified electrical heating engineer. Ask the heating engineer to explain the options, which might also include switching to other forms of electric heating.

### 3 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

### 4 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

## Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

## Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	7,696	(65)	N/A	N/A
Water heating (kWh per year)	2,179			

## About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst ([www.elmhurstenergy.co.uk](http://www.elmhurstenergy.co.uk)), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk) and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. John Strachan
Assessor membership number:	EES/009418
Company name/trading name:	Samuel and Partners
Address:	20 High Street Fort William PH33 6AT
Phone number:	01397 702686
Email address:	<a href="mailto:john@samuelandpartners.co.uk">john@samuelandpartners.co.uk</a>
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

## Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk), with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at [www.gov.scot/epc](http://www.gov.scot/epc).

### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

**HOMEENERGYSCOTLAND.ORG**  
**0808 808 2282**  
FUNDED BY THE SCOTTISH GOVERNMENT

